

"P O I N T   C L E A R."

Before this case receives consideration, IT IS  
SUBMITTED the Surveyors be requested to confirm that:

- (1) Shell plates in "L" & "K" strakes (p & s amids),  
"J" strake (psa) and "H" strake (ssa) have been  
dealt with.
- (2) The sternpost (fractured) connecting plate at  
top of A.P. tank previously recommended by the  
SINGAPORE Surveyors to be specially examined  
and dealt with as necessary at the Reclassification  
Survey, has been made good, and
- (3) The F.E. Report sent to them in 17.9.51 has been  
returned.

R.S.P.

4.12.51.



© 2020

Lloyd's Register  
Foundation

008231-008138-0071