

to Chief Surveyors

Received from Chief Surveyors

SEL'S NAME Steel S.D. "ETHAN ALLEN" Report Phl. No. 3728**For the CHIEF SHIP SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

are of Survey

When due

The Downrator Pump has been dispensed with for the present.

✱ 100 A.1. (steel) "Shelter Dk. with Freeboard"

1 Dk. (steel), & Shelter Dk (steel) and 2nd Dk (steel) forward.

Webframes. Longitudinal Framing.

Cell DB 344' 1364 t. MT 36' 838 t. Dta 21' 153 t. FPT 235 t. APT 174 t.

FIG. ⁵ BH to Shelter Dk. ¹ BH to upper Dk. Cem. A/C.P.

at 18/6/10

PA1', B134', F 46' on Shelter Dk.

See letter to "John Adams".

27-4-20

It is concluded the thickness of fore peak bulkhead stiffeners is as approved but the Surveyors should be requested to state if this is so.

8/0 19/5/20

yes
no with 11/6/10