

Empire Mountmain

hwc. 102296

X It might be pointed out to the hwc. Office that as the main
boilers were constructed under the supervision of the British
Corporation the record should be. L.M.C. * 8.44 & not
+ hwc. 8.44 as recommended

Should the accompanying Int Cert. B. & Rep. 10. have
been issued & they should be withdrawn & amended accordingly
to interested parties

Lloyd's Register
Foundation

008237, 008247-0096