

The greater part of the 2nd S.S No 3 has been held. (due 12, 41)

2m.10.39.

The class is subject to repairs being effected to tank under boilers at the Special Survey.

11 AUG 1941

1

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME Singo Maru. Rpt. Kob. No. 11772

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

ure of Survey DAMAGE.

Damage through contact with wharf.

now repaired as follows:-

	Shell Plates	Main Frames	R. Frames	Floors & Bracket Floors	Beams	Inner Bottom Plates	Deck Plates
Renewed	7	—	—	—	—	—	—
Removed and faired } or repaired..... }	2 pl	—	—	1	—	—	—
Faired or repaired } in place..... }	-	—	—	—	—	—	—

Other items:- stem bar part renewed

Vessel placed in dry dock & bottom coated

The Survey Confined to the above

It is submitted the vessel is worthy to remain as classed without record of Survey. Subject as above.

docking date 3.41



© 2021

8/8/41

Lloyd's Register
Foundation
S. S. Partly held