

F.E.

Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

NAME Steel S.S. "PEEBLES" Rpt. Mdb. No 10380

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.

Reference No. 83 Depth "d" 27.42

Drawing: Table No 3 page 16 Description Bulb angle & reversed frame, as approved.

Longitudinal No. 33200


Proportions $\frac{\text{Length}}{\text{Depth}} = \underline{10.2}$

Ridge Deck Sheerstrake as approved.

The ~~downton pump and kedge anchor~~ ^{has} been dispensed with as approved in Standard Vessels and it is concluded the Owners are agreeable to fit same at the end of the War if requested to do so.

This vessel appears to have been built in accordance with the approved plans, and it is submitted she is eligible to be classed \star 100 A.1. (Steel) as recommended.

1 Dk. (Steel).
Cell DB 345' 1058t. FPT 132t. APT 213t.
FK. 7 BH. pt.Cem. Lloyd's A. & C.P. P49', B113', F40'.


23. 5. 19.

27.5 berts not a name © 2020



Lloyd's Register Foundation