

7TH FLOOR, SHINKO BUILDING,
8, KAIGAN-DORI, IKUTA-KU
(P. O. BOX NO. 446)
KOBE, JAPAN

10.2.58

15th January, 1958.

Dear Sir,

"DOREA"

The above vessel was submitted for General Examination for postponement SS whilst lying at Kaohsiung, Taiwan, Formosa.

Mr. Cheshire, Senior Ship Surveyor, was appointed to attend this vessel, and upon arrival was advised that all three boilers had been prepared for examination including all mountings except the safety valves.

Mr. Cheshire reported that he examined the boilers internally including furnaces and back ends also all boiler mountings except the safety valves.

The following repairs were effected.

Starboard Boiler: Two smoke tubes renewed.

Centre Boiler: Main stop valve lid renewed.

The Boilers were reported to be in a good condition and free from heavy scale.

The Owners have agreed to submit the boilers for Survey again at the Special Survey, and in view of special circumstances in this case, it is submitted for the consideration of the Committee that in this instance the examination as carried out now be accepted without fresh record of Survey, subject to the boilers being re-examined at the Special Survey to be held in early June, 1958.

Repairs were effected to the Auxiliary Condenser by fitting a stopper to one leaky tube the condenser subsequently tested and found tight.

The Chief Engineer reported that no trouble had been experienced with the main engine or auxiliaries.

Yours faithfully,

Peter Mannon
For the Surveyors.

The Secretary,
LONDON.

ER

510-412800
For the Surveyors.

The Secretary,
LONDON.

13201

... had found no fault with the engine or with the main bearings reported by the Chief Engineer.

... the condenser and the boiler were also examined and found to be in good condition.

... the examination of the boiler was carried out by the Committee of the Surveyors and in view of special circumstances the boiler for Surveyors was appointed to be held in early 1901.

... the boiler was reported to be in a good condition and the boiler was also examined.

... the boiler was reported to be in a good condition and the boiler was also examined.

... the boiler was reported to be in a good condition and the boiler was also examined.

... the boiler was reported to be in a good condition and the boiler was also examined.

... the boiler was reported to be in a good condition and the boiler was also examined.

... the boiler was reported to be in a good condition and the boiler was also examined.

... the boiler was reported to be in a good condition and the boiler was also examined.

... the boiler was reported to be in a good condition and the boiler was also examined.

... the boiler was reported to be in a good condition and the boiler was also examined.

... the boiler was reported to be in a good condition and the boiler was also examined.

23.5.01

1-512

ИМАРАЛ КОВЕ
№ 0 BOX NO. 442
8' КИЕВИ-ДОМ' ИКУЛА-КУ
11. П. ГООР' ШИМКО ВУЛДИНГ

© 2020
Lloyd's Register
Foundation

