

Rpt. 8.

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of

No. in Reg. Book. Survey held at Date, First Survey Last Survey 19

13543 on the Wood, Iron or Steel T. Sc. SS. ITATINGA Master
TONNAGE:- Built at Uroon By whom Orlan S.B. Co. Ltd. When 1912 6
GROSS 2114 Owners Cia Nacional de Nav. Costeira Port belonging to Rio de Janeiro
UNDER DK. 1605 Owners' Address (if not already recorded in Appendix to Register Book)
NET 181

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage
WB=CellDBorDBa feet; uE&B feet; f feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, of the inner bottom plating, especially in the boiler space.

Report, No. 4426 Port Rio

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Year Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+ A - with 8th.		+ LMC 10.48
9.48		Ts 9.48 00
SS Rio - 10.48 (B)		
South American Coasting Service, Bahia Blanca		
Society's Freeboard (if assigned) as		
Painted on Ship and now verified		

Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; being detailed in the body of the report, should be summarised in the form shown below. Whenever the of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on this form. State also the dates and initials of any letters respecting this case.

ases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why declined? Was a damage report made by anyone else? If so, by whom?

OR EXAMINATION AS PER RULE, FOR

DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
1 ...								
d and Faired or Repaired ...								
or Repaired in place ...								

DITION OF THE

State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or I.M. of Wood Vessels
State if Tanks now tested	Engine Room Skylights	(State if on Felt.)
Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Ceiling	Scuppers	Boats
Cement or Asphalt	Cargo Hatchways	Masts, Yards, &c.
(State which.)	Hatches	Condition, how ascertained
Rudder	Planking of Wood Vessels	(State if wedges removed)
Steering gear and its connections	Caulking ditto	Sails
Windlass	Treenails ditto	Equipment letter
Have Pumps now been examined and found efficient?	Breasthooks & Stemson ditto	Anchors, No. o
Have Sluice Valves now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Have Watertight Doors now been examined and found efficient?	Timbers of Frame at openings ditto	„ length size
Have Ventilators and their Coamings been examined	Ditto ditto at other places ditto	(on board)
and found efficient?	Stringers, Clamps & Shelves ditto	„ Rule length size
	Salting ditto	Hawser & Warps
	(State if examined.)	Standing & Running Rigging

Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:—to remain as now classed in the Register Book without fresh record of Survey, "to remain as classed and to have record of 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

Section 28)	£	Fees applied for,
Charge or Repair Fee (if any)	£	19
Travelling Expenses (if chargeable)	£	Received by me,
Second Surveyor's Fee (if any)	£	19

Surveyor to Lloyd's Register of Shipping.

Committee's Minute 21. 23 SEPI 1919

Character Assigned

Withdraw class

insert (...)

Special General Committee
Thursday 13th October 1919
Classing Committee
decision confirmed