

4 E

Engineer Surveyor

Received from Chief Engineer Surveyor

18-2-47

IE "SAINTE BERNADETTE"

Rpt.

Alg. No. 1642

The Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also
point out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points
stated in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~----

Reclassification Survey.

The whole of the machinery and screwshaft
examined after damage by submersion.

Furnaces drilled for thickness all plain
and tubes renewed and welding repairs effected.

The working parts of the machinery cleaned
and machined where necessary and bearings remetalled and
all reconditioned with the exception of electrical equip-
ment where necessary materials remain to be supplied and
fitted.

IT IS SUBMITTED that the vessel WILL BE
eligible for the Record # LMC 5.46 when the electrical
equipment has been placed in order and a satisfactory
first Entry report on the electrical installation has
been received.

See endorsement attached dated 4. 9. 46.

Reed.

4. 9. 46.



© 2021

Lloyd's Register
Foundation

008641-008647-0215