



Collingwood Buildings, Newcastle-on-Tyne.

RECD 16 MAR 1915  
ANS

15<sup>th</sup> March 1915

The Secretary Sir

per 19/3/15

With regard to my report-  
No 67254 on ss Northwestern Miller I find  
that I have made a mistake in the  
fee which should be £106 <sup>20</sup> 13-0 and I  
shall be glad if you will be good enough  
to give directions for this to be corrected.

I have also to request that you will add the figures  $5\frac{1}{2}$  & 6 diameters as the spacing of the rivets through frames & plating in the space provided for the purpose on the report.

Regretting the necessity for these  
corrections I am Sir

Your obedient servant  
E. J. Mutton

Lloyd's Register  
Foundation

008648-008655-0234

acing good. . . . .	in fore hold	53	V	53						" Angles on dunnage . . . . .
Pool Deck, Angle, Bulk Angle, Plate, . . . . .		12	4	53	12	4	53			" Tie Plates . . . . .



Referred to the Chief Ship Surveyor.

*C.A.*  
MAR 16 1915

Referred to Mr. Ascough *MM*

*MM*  
16.3.15

REC'D TO MARINE  
LONDON  
LLOYD'S REGISTER



© 2021

Lloyd's Register  
Foundation