

Do. of Houses on Deck
Do. of access of Hatchways
Do above Crown of

Length on deck from fore part of stem to after part of
sternpost

419-42

By whom built

3m, 1, 15.

Received by Chief Ship Surveyor 13.3.15 Northwestern Miller

SEL'S NAME Steel ss Northwestern Miller Rpt. Inve No. 67264

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Remarks of Surveyor 1st Eng.

Before this case receives consideration the report should be
as Newcastle Surveyors requested to state whether the
division bulkhead extends to the shell deck & also the
spacing of the ribs connecting the frame & shell.
The size of the intermediate reversed frame in way of
the double bottom should also be entered on the report.

Ship Section to be returned to be amended and same marked on same.

15.3.15

Dr. Inve. 15.3.15



© 2021

Lloyd's Register
Foundation

008648-008655-0237

Angles on upper edge

Poop Deck Stringer Plate, breadth & thickness

Angles on ditto