

If the liner is in more than one length are the junctions made by fusion through the whole thickness of

"Kwantu Maru"

{ Yka. 4588
Bru. 1243.

It is submitted that
this vessel is eligible for
THE RECORD.

+ L.M.C. 9.30. C-L.

Oil Engines 12cy. $23\frac{5}{8}$ " - $35\frac{7}{16}$ " N.H.P. 2350
D.B. 100 $\frac{1}{16}$.



2021
30/10/30.

Lloyd's Register
Foundation

008679-008690-0332

and sufficiently high on the ship's side to be seen to detect any of the pipes or fittings

fitted with a Discharge Valve always accessible on the exterior of the vessel

Are the Blow Off Cocks fitted with a spring and