

2 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

"WINSTON CHURCHILL"

Rpt.

Sld.

No. 35240

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/02.)

Survey COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S.—No.

This Survey, due 7.49 now held partly

now

completed, and the following repairs carried out (due to wear & tear):-
A considerable number of plain tubes in all boilers renewed, also number of superheater elements renewed.

Alterations An oil fuel burning installation has now been fitted in accordance with the approved plans, also an additional feed water heater has been fitted and the position of the ballast and main discharge valves has been altered.


It is submitted the vessel is eligible to remain as classed, with

notation of

* LMC 11.49

as recommended.

"Fitted for oil fuel 11.49, F.P. above 150°F"



© 2020

(Clip M. de Lant Records)
2.1.50

Lloyd's Register
Foundation

00870-008752-0041