

18th September, 1959.

BUENOS AIRES

30595, 609 - As recommended.

RMC. 30697 - As recommended.

30684 "SAGOLAND" - As recommended and subject as previously recorded.

30691 "RESTAURADOR" - As recommended, except that class has been continued subject to rudder stock (twisted 7°) being specially examined and dealt with as necessary at the next drydocking and as previously recorded.

30581 "GENERAL LAS HERAS" - As recommended, except that class has been continued subject to anchor joining shackles (port and starboard) being tested to Rule requirements at the earliest opportunity and to rudder and sternframe (pitted) being specially examined at the next drydocking. The notation SS 6.59 has been withheld pending the completion of the Engine Survey.

Lloyd's Register

668751-4076210092