

"Z A H R A"

Before this case receives the consideration of the COMMITTEE, IT IS SUBMITTED the Lloyd's Agents' Surveyor at CASABLANCA be informed it is concluded the storeroom, engine and boiler spaces, pump room, general equipment, ventilators, air and sounding pipes have been examined, the peak tanks, bunkers and D.B. tanks internally examined and tested, and the freeboards verified, but he should confirm this.

He should be requested to state the length of the chain cables on board, and their mean diameter, and the number of bower and stream anchors on board.

JMB
20.4.49.

[Signature]



© 2021

Lloyd's Register
Foundation

00 8753 - 00 8758 - 0158