

"SURINAM" (S.S. due 3,54)
(B.S. due 1,54).

Over 35 years old.

at to Chief Surveyors "TAMARE" (S.S. due 8,53)
(B.S. due 6,54)

do Received from Chief Surveyors.....

SHIP'S NAME "ULE" (S.S. due 11,53).
(B.S. due 11,53).

do REPORT No.....

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey..... When due.....

The Surveyors in reply to letter dated 14.10.54 should be informed:-

- (1) before these ships proceed to Victoria, B.C. in tow, a comprehensive General Examination indrydock is to be held on each ship and each found or placed in a satisfactory condition.
- (2) If Owners decide to retain classification the full requirements of a SPECIAL SURVEY (D) should be complied with including drilling of shell and deck plating, and
- (3) should the Owners' proposal to convert these tankers into barges be carried out, plans of the alterations will require to be submitted for approval.



S.P.S.
20-10-54
2021
Lloyd's Register
Foundation