



LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

P.O. Box 175, San Nicolas, Aruba, N.A.

Telegrams: Register, Aruba

Telephone No. 3181

28th May, 1954

Reference

The Secretary,
London.

Dear Sir:

RECEIVED

1 - JUN 1954

Encl.....

I wish to acknowledge receipt of your cable of May 21st, 1954, as follows:

REURCABLE ULE SURINAM COMMITTEE REQUIRE
SATISFACTORY GENERAL EXAMINATIONS IN DRY
DOCK ACCORDANCE CIRCULAR NO1959 ALSO BOILER
SURVEYS CARRIED OUT AND PORT MAIN CRANKSHAFT
AFTER COUPLING OF SURINAM EXAMINED.

I wish to advise I have now received further advice from the Owners that they have abandoned their intention of reactivating these vessels, and the vessels will continue to be laid up at Maracaibo.

Yours faithfully,

W.D. Wardle



© 2021

Lloyd's Register
Foundation

008759-008784-0026

