

The class is subject to LP piston repairs being specially examined before the end of 1,57.

26 MAR 1957 4E

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

NAME.....

"MEAD"

REPORT.....

Drb.....

No.7379

Repairs effected to boiler.

SRL. LP piston repairs specially examined and remain satisfactory. Surveyor recommends these repairs be again examined at the Special Survey or before the end of 5,57.

IT IS SUBMITTED that this vessel is eligible to remain as classed, subject as now recommended, and without other special conditions.



26.3.57

© 2020

Lloyd's Register Foundation

008765 - 008772 - 0106

May, 1957.

nanocv  
wor  
ton

special survey and in any case before