

LONDON

COPY.

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER



S.S. II
 L.S. II
 Port BUENOS AIRES
 TO ACCOMPANY BUENOS AIRES REPORT N^o 29426
 11th. August, 1958.-
 DATED _____

This is to Certify that I have

Surveyed the Boilers and Machinery of the S. Tanker "GENERAL SAN MARTIN", 12759 tons gross of Buenos Aires, on 16th. July 1958 & subsequently, whilst the vessel lay in drydock at Bahia Blanca, for Tail Shaft, Main Boiler, Donkey Boiler and Steam Generator Surveys and machinery repairs,

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have Recommended that the record of TS (CL) 7.58 now, M.B.S. 7.58, D.B.S. 7.58 and SGS 7.58,

be made in the Register Book in the case of this vessel when the survey has been completed, subject to the starboard donkey boiler not being used until repaired as previously recommended, and also subject to main L.P. turbine blading being re-examined by 6,60(2 years limit).-

Parts now examined:—

Propeller, sternbush, sea connections, fastenings, and tail shaft.
 Low Pressure turbine blading.
 Port and Starboard main boilers and mountings.
 Port donkey boiler and mountings and steam generator and mountings.

To complete M.B.S.:— Safety valves of both boilers to adjust under steam and oil burning system to examine working.
 To complete D.B.S.:— Safety valves of Port D.B. to adjust under steam and oil burning system to examine working.
 To complete S.G.S.:— Safety valves to adjust under steam.

James S. Cook.
 Engineer Surveyor to Lloyd's Register.
 J.S. Cook.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
 While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or in the publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or of its Surveyors, or other Officers or Agents of the Society."

(S.) 3000-9-55

008785-008788-0079