

"INSUMAR"

This ship was built 1953-10 and then<sup>+</sup> ✓  
classed #100A1.

A SPECIAL SURVEY was held and a notation ✓  
"SS Sba. 5,57" was assigned.

The class was subsequently withdrawn at ✓  
Owners' request 9,58.

In a Telex received 11.3.59 from the  
SOURABAYA Surveyors, it is stated that the Managers of  
this ship were unaware that the class had been withdrawn,  
and requesting instructions as to whether drydocking  
and modified Engine Surveys might now be proceeded with.

IT IS THEREFORE SUBMITTED for the favourable  
consideration of the Committee whether -

*M.H.*  
(a) a satisfactory General Examination be held  
for reinstatement of class and  
notation of "SS Sba. 5,57", provided the  
Surveyors are satisfied that no structural  
alterations have been effected since the  
class was withdrawn,

OR

(b) a full Special Survey be now held.

*For re-instatement  
of Class, it is Submitted  
that it would be sufficient  
to carry out Modified Engine  
Survey and drydocking*

*M.H.*  
12.3.59.

*12/3/59.*

© 2021

Lloyd's Register  
Foundation

008804 - 0088 11-0131