

ived by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor..... 15 OCT 1959

IP'S NAME..... INSUMAR..... REPORT Sby..... No. 6252

Vessel's class was withdrawn in 9.58.

Docking. Screwshaft examined.

The machinery survey requirements for re-instatement of class as laid down in endorsement dated 12.3.59 have now been complied with.

It is submitted that this vessel's machinery is eligible for re-classification, for the approval of the Committee.

with notation + LMC. 4.59.

Alb.

14.10.59.



© 2021

Lloyd's Register
Foundation

008804-008811-0134