

3 E

2 AUG 1956

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

Suez

567

NAME

"FOUADIEH"

REPORT

Suez

No. 575

the remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

SPECIAL SURVEY OF ENGINES AND/OR BOILERS PARTLY HELD.

LMC

~~LMC(M)~~

due 6,56 , partly held now.

~~ME~~~~BS~~

~~Now further advanced and the following repairs effected (due to~~

Forward main boiler found defective, and the Surveyors recommend it be not used until repaired.

It is proposed to complete the Survey - not stated.

It is submitted that this proposal merits approval and the vessel is eligible to remain as classed, and WILL BE eligible for the record

+LMC 7,56 when the Survey has been completed, BS 7,56 now subject to the forward main boiler not being used until repaired.

The following remains to be done to complete the Survey:-

All Rule requirements to be carried out except examination of:-

of Outboard feed pump,
Main engine driven pumps,
Main circulating pump, → and Port and starboard feed pump, and
Fan engine. General service pump.

Note for RE- Delete forward boiler with thin red line.

NOTED FOR
POSTING

Noted
for
Header



© 2021
31.7.56.

Lloyd's Register
Foundation

008823-008830-0041