

Received from Chief Ship Surveyor

115 DEC 1952

SHIP'S NAME MATELOTS PILLIEN & PEYRATREPORT DunkirkNo. 4345

Outstanding Conditions of Class: Subject to the bow anchor (supplier Rot. 9.50)
Being tested at the earliest opportunity.

Enhorsement of Class (B) (~~As before or None~~)

Surveys due:

A Special Survey (B) became due 5.52 but postponement until
11.5v approved by a General Examination carried out Sch. 3.52

Nature of Present Survey: (Afloat and in dry dock)

Commencement of Special Survey (B)

Fitting of W.T. door to bullehead between E.R. & Tunnel

Special Features:

The owners state that the S.S. will be completed on ship's
return to France early in Dec. 1952

Is Interim Certificate in order (Yes-No-None)

Items Outstanding: (If any for S.S. or A.S.)

See OVER

S.S. to be completed by: 11.5v

Recommendation:

Subject as above but ACTION & NOTATION of S.S. Dnk 9.5v
be DEFERRED for completion of Special Survey & repairs

As now. Subject



Lloyd's Register
Foundation

008831 - 008838 - 0020

To complete the S.S.

Examine. ✓ In dry-dock, anchors & cables, chain lockers,
✓ plating in way of sidelights, steering gear,
No 6 & 7 D.B. tanks and E.R. deep tanks internally
Centre O.F. bunkers internally
Test Oil fuel D.B. tanks, centre O.F. bunkers, E.R. deep tanks,
No 6 & 7 D.B. tanks ✓

Repairs to be effected to buckled floors in No 7 D.B. tank (p.s),
✓ wasted plating & stiffeners of tunnel in way No 8 D.B. tank
✓ Defective shell rivets, on p.s. aft and main mast shroud.

Office note

See letter dated 28.8.57 re waiving of internal
examⁿ of O.F. D.B. tanks



© 2020

Lloyd's Register
Foundation