

2m.8.46.

mw

25 AUG 1947

t to Chief Surveyors.....

Received from Chief Surveyors.....

SSEL'S NAME EMPIRE FULHAM REPORT Lon. 115227A
No.....

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER-SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

re of Survey..... When due.....

The class is subject to permanent repairs to stem and stem plating and indented side and bottom shell plating etc. (p & s) at the first opportunity.

The Admiralty state, in a letter dated 10th July 1947, that it is not desired to maintain this vessel in classification.

It is therefore submitted the vessel's character be deleted from the Register Book and three dots inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class
and insert (...)

1,47.



© 2020

Lloyd's Register
Foundation

Mel
22-8-47
B.M.

008831 . 008838 . 0205