

S.S. Dicto. S. Fo. Rep't No 2543.

These paired turbines have been taken out of vessel, & replaced by reciprocating machinery - See Glasgow report No 42878 attached to Newcastle report No 83889, dated 5/3/29.

J.M.  
27.8.29

Lloyd's Register  
Foundation

608909-008916-0065