

Received from Chief Ship Surveyor

27 MAY 1960

SHIP'S NAME "HOYO MARU

REPORT YKA

No. 3230

EA

Outstanding Conditions of Class: NONE

S.R.L. Appendix. (XXXXXXXXXXXX) (As before or None)

Nature of Present Survey: (Afloat and in dry dock)

Docking. Permanent/deferred wear and tear repairs.  
Damage repairs (various causes).  
Equipment - renewal and verification of 45 fathoms of chain cable  
at ~~XXXX~~ request~~s~~.  
Owners

Recommendation: SUBMITTED record of DS 4,60 be assigned subject to No.2  
double bottom tank top plating being specially examined and dealt  
with as necessary by the Special Survey.

DS 4,60 SUBJECT

NOTE. Owners representative states ship is to be withdrawn from class but  
this has not been confirmed.

IT IS FURTHER SUBMITTED the Surveyors be advised that in  
view of the outstanding repairs of No.2 D.B. tank it  
cannot be accepted for S.S.

Blk (new)

to No. 2 DB tank top plating being specially examined and dealt with as necessary at com

008917-008924-0077