

Lloyd's Register of Shipping.

14, Cross-shore Street,

Greenock, 19th February, 1937.

LLOYD'S REGISTER
GLASGOW

20-FEB-1937

ANSW.....

Reference


Dear Sir,

In reply to your letter of 18th instant, with regard to the Greenock Report No. 20311 on the Steamer "DARLENY", I beg to state that the outboard channel vertical strut of the bracket floor is 8" as noted on the First Entry Report. The Builders desired to make this alteration from the original approved size of 10", and in view of the decreased span and the Rule requirement as per Table 7a, this was agreed to and no exception taken by the Owners' representative.

I trust this will be in order.

I am, Dear Sir,

Yours faithfully,



The Secretary,

GLASGOW.



© 2021

Lloyd's Register
Foundation

008917-008924-0084
0011-0000-0000
008917-008924-0084

Spacing.....