

LLOYD'S REGISTER OF SHIPPING

c/o DAVIE SHIPBUILDING & REPAIRING CO. LTD.

Lauzon, P.Q.

6th July, 1950

Mr. A. R. Riddell,
Principal Surveyor for Canada,
Lloyd's Register of Shipping,
751 Victoria Sq. Bldg.,
Montreal, P.Q.

S.S. "LOUIS JOLLIET"

Dear Sir:

We are in receipt of your letter of the 4th inst. in which you quote an extract from Classing Letter received from London.

In reply thereto we wish to state that all rule requirements for Special Survey on the above-named vessel were carried out but it is regretted that the method of reporting same was not made clear.

- (1) (pt. exd good) should read, "good".
- (2) (Ceiling in bunkers only) "good".
- (3) W.T. Doors (none fitted).
- (4) Deck W.T. scuttles and W.T. manholes, good (no cargo hatchways).
- (5) There are no holds. (Ballast tanks ford. and Machy spaces aft).
- (6) Accommodation and stores spaces reported under tween decks.
- (7) Mast & rigging (signal pole).
- (8) Anchor, one off 75 fms. cable 7/8" dia.

Yours very truly,

(Sgd) R. D. Campbell

FOR THE SURVEYORS

© 2020

Lloyd's Register
Foundation