

'LOUIS JOLLIET'

Before this case receives consideration IT IS SUBMITTED the QUEBEC Surveyors be informed it appears from their report the requirements of the Periodical Spécial Survey (C) due 5.51 have not been complied with.

Several items are marked as only being "part examined". The condition of the reverse frames, ceiling, cement, W.T. doors (if any), deck openings and their closing appliances and chain locker are not reported upon. Particulars of the equipment of anchors and chain cables on board should be furnished even though the figure '1' is not assigned. The masts have only been examined "from deck" and not as required by the Rules.

It appears therefore that to complete the Special Survey, the following items remain to be dealt with, but this should be confirmed :-

EXAMINE :- All hold, accommodation and store spaces, decks, hatchways and deck openings with their closing appliances, chain locker, masts, rigging, W.T. doors (if any).

The Interim Certificate dated 22<sup>nd</sup> May 1950 should be cancelled.

*[Signature]*  
27.6.50