

COPY

25th April, 1947.

ALGIERS.

1676. TEMARA. As recommended. The thicknesses of the shell plating as ascertained by drilling indicate a gradual diminution of approximately 25% below the original thicknesses and are therefore not such as could be recommended for a record of S.S. 1,47 (Dr). The notation therefore of S.S. 1,47 (without the qualification regarding drilling) recommended by you is concurred in and it is considered that the drilling of the plating may be deferred in this instance until the vessel is 30 years old instead of at the first Special Survey after she is 24 years old.



© 2020

Lloyd's Register  
Foundation

008993-009003-0384