

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

FOUNDED 1760


RE-CONSTITUTED 1834

Certificate of Class

Steel Screw Motorship "HIYEHARU MARU"
Official Number 70180 Port of Registry Nishinomiya
Owners Shinnihon Kisen K.K.
Builders, and where and when built Mitsubishi Heavy Industries Reorganized Ltd., Kobe,
October, 1953.

REGISTERED PARTICULARS


| | | | |
|---------|-------------|------------------|---------|
| Length | 448.82 feet | Tonnage, Gross | 7846.39 |
| Breadth | 60.70 feet | Ditto under Deck | 6878.09 |
| Depth | 37.40 feet | Ditto Net | 4435.94 |


This is to Certify that this Ship has been built under the Special Survey of
the Surveyors to this Society, and was reported to be, on the 24th October, 1953
in a fit and efficient condition as is prescribed by the Society's Rules for the safe carriage of
dry and perishable or other approved Cargoes, and has been CLASSED and entered in the
REGISTER BOOK of this Society, with the Character  100A1
Carrying oil fuel flash point above 150°F. or vegetable oil in deep tanks.
subject to Periodical Surveys as required by the Rules.

The approved minimum freeboards from the deck line are as follows:—

| | | | |
|----------|---------------------------|--------------------------|--------------------------|
| Tropical | 2716 feet mm. inches (T). | Winter | — feet mm. inches (WNA). |
| Summer | 2894 feet mm. inches (S). | Allowance for fresh | |
| Winter | 3072 feet mm. inches (W). | water for all freeboards | 184 mm. inches |

Witness my hand,


pro Secretary,



Chairman.

71, Fenchurch Street, London, E.C.3. 12th January, 1954.

N.B.—If the ship herein named proceed to sea with a less freeboard than that approved by the Committee, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



Lloyd's Register
Foundation



© 2021

Lloyd's Register
Foundation

009004-009007-0122