

Surveyors 3-12-17

Received from Chief Surveyors

NAME SR 3 'War Cypress'

Report Dis

No. 77174

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Survey

1st Entry

When due

* 100 A1 (Steel)

1 BA (Steel)

Cell RB 343' 1152 C. FPT 113 C APT 166 C.

FK. 7 BH, pr cem, P 49' B 113', F 40'. Lloyds A + CP.

M

ME.

3-12-17

cluded that the spacing of the 1" rivets in the landing edges
beerslake & stroke below ^{and of the rivets through frames & shells} is in accordance with the rules
so that a web frame & the 2nd deck beams & plating have
been fitted in the E + B space in accordance with the approved plans
Surveyor should be requested to state if this is so.

M

Please pass report to Mr. Mayne after

letter to Lloyd

© 2020



Lloyd's Register
Foundation

009040-009049-0022

BE

BEAM

BEAMS,