

COPY.

# Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

30th October, 1934.


Dear Sir,

With reference to the classification in the Society's Register Book of the steamer "ALIKI", I beg to acquaint you that the Committee have had before them today a report from the Society's Surveyors at Buenos Aires, from which it appears that the vessel has been examined as far as practicable afloat after grounding.

Soundings were taken and no leakage was found and so far as could be seen no damage had been sustained, but it is recommended that the vessel be examined in dry dock at a home port, after the discharge of her present cargo.

I take the opportunity to refer you to your letter of the 21st December of last year, addressed to the Society's Surveyors at Piraeus, requesting to be allowed the year of grace for the Second Special Survey No. 1 which became due in November, 1933, and as this period will expire at the end of next month, it is concluded that the survey will be taken in hand when the vessel is dry docked, on the discharge of her present cargo as mentioned above.

I would add that repairs require to be effected to the bridge deck house side plating on the port side at your



© 2020

Lloyd's Register  
Foundation

009040-009049-0050 1/2

COPY.

convenience, as previously recommended

I am, Dear Sir,

Yours faithfully,

Clerk to the  
Classification Committee.

N. G. Livanos, Esq.,  
Megaron Vati,  
PIRAEUS,  
Greece.



© 2020

Lloyd's Register  
Foundation

009040 - 009049 - 0050 2/2