

Original letter with: 4

Copy of ~~Extract from~~ letter received from

NAME Surveyors,

ADDRESS Durban.

Reference, if any:

Dated 16.7.55 Received 20.7.55 Answered 4

Vessel's Name: "VOORTREKKER" and "BOUNDARY"

In reply to your letter Classn.(H) of the Bth instant in connection with the renewal of wood sheathing in the forward tween deck of the Steamer "BOUNDARY", we have to advise you that the Owners have been contacted and we give the following details of their arrangements for dealing with outstanding surveys on the two above named ships.

The floating dock was booked for the "VOORTREKKER" for mid-July so that she could commence Special Survey.

Unfortunately one of the same company's ship the "BORDER" which is undergoing Special Survey is still on the floating dock and will not undock for at least another 10 days.

When the "BORDER" undocks the "VOORTREKKER" will follow for docking and Special Survey.

The "BOUNDARY" will then follow the "VOORTREKKER" for interim docking and renewal of wood sheathing in forward tween deck. It is anticipated this will be about the end of August.

We trust that these arrangements will be satisfactory and we shall keep in contact with the Owners and if there is any further delay we shall keep you advised.



© 2021

Lloyd's Register
Foundation

009067-009073-0139