

6,500,10,40.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSELS NAME

'HOLLAND'

REPORT

Drb

No. 5515

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class of this ship was withdrawn 24.11.50 and 3 dots inserted in lieu, thus (...)
11.50 ←

The DURBAN Surveyors report 9.50, ship examined in drydock, bottom coated and on account of wear and tear, repairs effected to shell plate E.7 (p.s.) and a few other items. This report was furnished as requested, see letter dated 28.11.50 to the Surveyors.

In view of the Committee's subsequent decision as above, IT IS SUBMITTED no further action need be taken.

Ly 8
12
50



© 2021

Lloyd's Register
Foundation

009067-009073-0142

A.R.