

Rpt. 8.

CLASSED SECTION.

Office 221. London No. 113308A

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of...

No. in Reg. Book 24315 32105 Survey held at on the Wood, ~~Iron~~ Steel S.S. "RIO VERDE" Date, First Survey... Last Survey... 19... (No. of Visits...)

TONNAGE: GROSS 611, UNDER DK, NET 278. Built at Lowestoft By whom J. Chambers Ltd When 1921 5. Owners: Cia. Belenadela Mar Interociano Owners' Address... Managers: M.R. Laming Port belonging to Punta Arenas

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage... Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of S.S., if any).
+ 100 A1 9,43 No. P. Ar. No 3-5,41	+ 2 MC 5,41 BS 5,44 TS CL N 9,43

All alterations in the existing records should be underlined.

Report, No. 9749. Port La.

Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below.

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

CATEGORY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place ...								

GENERAL CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.) When fitted, Month
Decking	Ceiling	Coal Bunkers, Openings, Covers, &c.	
Plating	Cement or Asphalt	Oil Bunkers	Boats
Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Plating in way of sidelights	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained. (State if wedges removed.)
Frames	Windlass	Hatches	Equipment letter
Fastenings	Have pumps been examined and found efficient?	Planking	Anchors, No.
Plating	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State length Rule)
Fastenings	Have Watertight Doors been examined and found efficient?	Treenails	Chain Lock
Plating	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Hawsers & Standing at
Fastenings	Air and Sounding Pipes	Transoms, Pointers & Crutches	Sails
Plating	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	
Fastenings		" " at other places	
Plating		Stringers, Clamps & Shelves	
Fastenings		Salting (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book without fresh record of Survey, "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Fee (per Section 29)	Damage or Repair Fee (if any)	Expenses (if chargeable)	Surveyor's Fee (if any)	Fees applied for	Received by me
£	£	£	£	19	19

Surveyor to Lloyd's Register of

FRI. 8 FEB 1946

© 2021

Lloyd's Register Foundation

Committee's Minute... Character Assigned... Cablewhite La... Lowestoft

Expenses also with Slack... white La.