

3m.7.28.

1

009083-009093-0048

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME St Se PEVERIL Report Rev No. 95531**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey 1st Entry When due _____ Revised Rule

✠ 100 A. I. (Steel). With Heelboard.


1 D* (pt^l Leaks)

Cell D.B a. v E 61' + 50' 1415, F.P.T. 435, A.P.T. 285

B.K 7", 7 B.H., Cew, Lloyd A CP

B 69', F 39'.

$$\begin{array}{r}
 69 \\
 39 \\
 \hline
 108 \times 6 = 648 \\
 60 \times 4 = 240 \\
 \hline
 888 \\
 1032 \\
 \hline
 1920
 \end{array}$$



© 2021
17.6.29

Lloyd's Register
Foundation