

1

13 SEP 1940

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME "GOVERNOR WRIGHT" Report Lon No. 109003a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

Nature of Survey _____

When due _____

No Survey is due on this vessel.

In reply to an enquiry, the Manila Surveyor now encloses a letter from the Owners requesting the class be withdrawn.

It is submitted the class of this vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request. .

Withdraw class.

Insert ...

R.G.D.

Y.R.

12.9.40



© 2021

Lloyd's Register
Foundation

009116.009121.0035