

NAB.

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

30th March, 1951.

Dear Sirs,

Classn. (H).

With reference to my letter of the 13th ultimo addressed to the Owners, a copy of which was forwarded to you, respecting the steamer "REG III", I shall be glad to learn how this case stands as regards the renewal of the manhole door studs of the centre boiler and the stoppered smoke tube centre fire of the starboard boiler and the examination of the fractured shell plate (F.2 on starboard side aft).

I think it well to add that since writing the above mentioned letter a report has been received from the Malmo Surveyor intimating that the port boiler has been examined and all the safety valves adjusted. The vessel will, therefore, be eligible for the record BS 12.50 when the above repairs have been effected.

Yours faithfully,

The Surveyors,
HAMBURG.

Clerk to the
Classification Committee.

009139.009143.0026