

Vancouver B.C.

RPT. 642

S.S. "ALASKA"

It is submitted the New York Surveyors should be requested to state whether the screw shaft of this vessel is fitted with a continuous liner and, if not, whether the joints have been burned as required by the Rules.

These particulars are not stated in the report.



© 2020

Lloyd's Register
Foundation

009139-009143-0081

Per centages of strength of longitudinal joint

plates

53.29

No. and Description of Furnaces in each Boiler 3 in Morrison's Material