

In damage cases where the Surveyor has not made a special damage report he is required to state whether he

WOKINGHAM COPY.

NLT

LLOYDS REGISTER  
RIODEJANEIRO

(5. 5. 45.)

YOUR REPORTS 37912 DRILLINGS APPEAR CONFUSED AS 3791 NO STRAKE H  
ORIGINALLY FITTED and 3792 FINISHING AT G STRAKE STOP CABLE WHETHER  
THICKNESSES REPORTED 3791 REFER RAISED QUARTER DECK SHEERSTRAKE G  
AND FOUR STRAKES BELOW AMIDSHIPS AND AFT AND UPPER DECK SHEERSTRAKE  
F AND FOUR STRAKES BELOW FORWARD AND FOR 3792 FURNISH THICKNESSES  
ASCERTAINED BY DRILLING RAISED QUARTERDECK SHEERSTRAKE H AMIDSHIPS  
AND AFT

LLOYDS REGISTER



© 2020

Lloyd's Register  
Foundation

009139-009143-0274

Floors ..... good

Have Watertight Doors been examined and found

Transoms, Pointers & Crutches.....