

Lloyd's Register of Shipping.

18 $\frac{1}{2}$, Regent Quay,

Aberdeen, 28th February, 1920.

LLOYD'S REGISTER
LONDON.

REC'D 1 MAR 1920

ANS'D

The Secretary,

LONDON.

Sir,

With reference to Aberdeen Report No. 12394 on the main boiler for the Steamer "Striver", the area of the safety valve was inadvertently stated to be 7.56 square inches instead of 5.93 square inches, and I have to request that the correction will be made on the Report.

Regretting the error.

I am, Sir,

Your obedient Servant,

Mr. Wilson. per. J. Murray.



© 2020

Lloyd's Register
Foundation

009139-009143-0298

Referred to the Chief Engineer Surveyor.

J. A. M.

Also for Mr. S. A. Hill to note.

Noted on Apr

JWD.
2/3/20

NOT RECORDED

THE

NOTE

REPORT NO. 12345 ON THE MAIN DOCK
-TREVILLAN AND OTHERS THE TO BE THE "TREVILLAN"
REPORT NO. 12345 TO BE THE "TREVILLAN"
REPORT NO. 12345 TO BE THE "TREVILLAN"

12345



© 2020

Lloyd's Register
Foundation