

Angles, Top

6

6

1.50

6

1.50

S.S. Sheaf Spear

Ld 27417

Ld surveyors should be informed it is concluded that
 3 1/2" bulb sections have been fitted in the trussing space
 of this vessel, but as this has been omitted from the 1st entry
 it should be requested to confirm this

H.D.

4/2/19

J.M.

Angle, Plate, Tee Bulb, or Channel
 In way of Long Bridge

1

"

"

1

"

"

Fourth and Fifth Deck Stringer

breadth &

Angles on ditto, No.

009222-009231-0013

Lloyd's Register
 Foundation