

DISCLOSED

SECTION

393

No. 115301

PORT SURVEY REPAIRS, &c.

Report made in at Local Office

Port of LONDON

Survey held at Date, First Survey

Last Survey

19

Book.

on the Wood, Iron or Steel Sp "Amos"

(No. of Visits)

TONNAGE :-

GROSS 430

UNDER DK. 352

NET 195

Built at Paisley

By whom J. Fullerton & Co.

When 1907

MONTH 8

Owners A/S Roderick "Anhalt"

Owners' Address

(If not already recorded in Appendix to Register Book)

Managers R.L. Albertson

Port belonging to

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

Cell DBor DBa feet; uE & B. feet; f. feet
total capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B. All alterations in the existing records should be underlined.

Last Report, No. 104367 Port N.W.C.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER.

* for Special Survey.
Date of last Survey and of
Periodical Surveys.

Machinery and Boiler

Surveys
(Including date of N.B., if any).

+ A - 9.46

+ Lmc 6.41

Examined 3.46

BS 3.46

ss Bly 2nd No. 3 - 7.30

IS CL 8.46

ss Mil No. 3 - 6.41

Cargo battens not fitted.

Coasting ft. Britain & Ireland (except West

Coast, Cork to Pentland Firth and Continent

from Breck to Hamburg. laid up pending Survey.

Society's Freeboard (if assigned) as ft. ins.

painted on Ship and now verified

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-

Shell Plates.

Frames.

R. Frames.

Floors and
Bracket Floors

Beams.

Inner Bottom
Plates.

Dk. Plates.

Other Items :-

Renewed ...

Removed and Faired or Repaired

Faired or Repaired in place ...

PRESENT CONDITION OF THE

Decks

Caulking of Decks

Coamings

Beams & Fastenings

Outside Plating

" " in way of sidelights

Frames

Reverse Frames

Longitudinals

Transverses

Floors

Keelsons

Stringers

Inner Bottom Plating

Have the Tanks been examined internally?

Have the Tanks been tested?

Bulkheads

Ceiling

Cement or Asphalt

Rudder

Steering gear and its connections

Windlass

Have pumps been examined and found efficient?

Have Sluice Valves been examined and found efficient?

Have Watertight Doors been examined and found efficient?

Have Ventilators and their Coamings been examined and found efficient?

Air and Sounding Pipes

Doubling Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Openings, Covers, &c.

Oil Bunkers

Scuppers

Cargo Hatchways

Hatches

Planking

Caulking

Treenails

Breasthooks & Stimson

Transoms, Pointers & Crutches

Timbers of Frame at openings

" " at other places

Stringers, Clamps & Shelves

Salting

State if examined.

Copper, or Y.M.

(State if on Felt.)

When fitted, Month Year

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if worked removed.)

Equipment letter

Anchors, No. of

Cables (State if now ranged)

" length mean diam.

(on board.)

" Rule length size

Chain Locker

Hawsers & Warps

Standing and Running Rigging

Sails

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)

Fees applied for,

Special Damage or Repair Fee (if any)

Received by me,

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

FRI. 30 JAN 1948

Committee's Minute

Character Assigned

Surveyor to Lloyd's Register of Shipping.

Special General Committee

Thursday 19th February 1948

Classing Committee

Decision confirmed 1948

009222-009231-0202