

Less above Crown of)

Length on deck from after part of stem to fore part of stern post

158.98

Owners *Antonio*

Managers *L*

1

Sent to Chief Surveyors

20/8/07

Received from Chief Surveyors

VESSEL'S NAME

St St La Plata

Report

GL

No.

25037

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

First entry

When due

+ A-1 (Stat) For River purposes only"

1st (Stat)

WB = F.P.T. 325

F.K. 3BH. Com. Lloyd. at 60. F.16

Tw

R.B.H.

20/8/07



© 2021

Lloyd's Register
Foundation

009222-009231-0207

" Hold "

Quarter 'tween Deck

Forecastle Deck Stringer Plate, breadth & thickness