

s.s. "SLASK" of Gdynia.

A/S. Nakskov Skibsværft's Yard No. 51.

List of Spare Gear.

Main engine:-

- 1 eccentric belt.
- 2 main bearing bolts.
- 1 set of piston rings for each cylinder.
- 10% of the studs for cylinder covers.
- 2 connecting rod top end bolts.
- 2       "       "       bottom end bolts.
- 2 nuts for do.
- 2 split pins for do.
- 2 H.P. inlet valves.
- 2 H.P. inlet valve seats.
- 2 intermediate valves.
- 2       "       "       valve seats.
- 4 L.P. valves.
- 4 L.P. valve seats.

Valve lifting gear:-

- 4 spindle bushes.
- 2 spring spindles.
- 4 valve spindles complete.
- 6 rollers.
- 6 bolts.
- 4 valve springs.
- 1 bilge pump valve.
- 1       "       "       "       seat.
- 20 condenser tubes.
- 25 screw ferrules.



© 2020

Lloyd's Register  
Foundation

009232 - 009234-0020 1/4

2.

2 air ejector jets.

2% of the tubes in the intermediate condenser.

1 piston rod for the condensed-water pump.

1 set of valves for do.

Feed pumps:-

$\frac{1}{2}$  set of valves.

$\frac{1}{2}$  set of valve seats.

1 set of steam piston rings.

1 set of pump " "

General service pump:-

1 valve.

1 valve seat.

1 set steam piston rings.

1 " pump " "

Ballast pump:-

1 valve.

1 valve seat.

1 set of steam piston rings.

1 set of pump " "

Circulating water pump:-

2 guide shoes.

1 crank pin brass.

1 piston rod.

2 piston rings.

1 eccentric rod with strap.

1 set of crosshead brasses.

1 cast iron impeller.

Shafting:-

1 set of thrust bearing blocks.

1 set of coupling bolts with nuts and split pins.

3.

1 propeller shaft with liner complete.

1 nickel steel propeller.

12 lignum vitae strips for sternbush.

Boilers:-

4 water gauge glasses.

2 safety valve springs.

18 plain tubes.

3 stay tubes.

6 tube stays.

1 set of fire bars for one boiler.

Superheaters:-

30 closing dials.

8 dogs.

8  $\frac{3}{4}$ " studs.

200 packings.

Feed water preheaters:-

1 spring for compensating valve.

1 safety valve spring for water.

1 " " " " steam.

12 water gauge glasses with packings.

Fan:-

1 set of crank pin brasses.

2  $\frac{1}{2}$ " of main bearing brasses.

1 eccentric rod with strap.

1 set of piston rings.

Electric light engine:-

1 set crosshead brasses.

1 guide shoe.

1 set of crank pin brasses.

2 piston rings.

1 eccentric rod with strap.



© 2020

Lloyd's Register  
Foundation

009232 - 009234 - 0020 3/4

- 1 governor spring.  
 8 carbon brushes.  
 2 brush holders.  
 1 escape valve spring.

Steam steering engine:-

- 1 set of main bearing brasses with studs.  
 1 set of crank pin brasses with keeps.  
 1 set of crosshead brasses " "  
 1 piston with rings.  
 1 slide valve spindle with nuts.  
 1 set of leather collars for telemotor.  
 1 valve for telemotor-receiver.  
 1 valve spring for do.

Windlass:-


- 2 piston rings.  
 1 set of crosshead brasses.  
 1 crank pin brass.  
 1 slide valve rod with nuts.

Cargo winches:-

- 2 crank pin brasses.  
 2 piston rings.  
 4 slide valve rings.  
 2 crosshead brasses.  
 2 slide valves.

Sundry:-

A number of assorted bolts and studs with nuts, washers,  
 flat and round steel of various dimensions, steel & brass  
 sheet, copper wire and packing material &c.



© 2020

Lloyd's Register  
 Foundation

009232 - 009234 - 0020 4/4

quad. Stem.

1890-1891

NAM

(“The en  
to br  
prese

If

This

ote

[illegible]

I clauk hyr ol gaa.

1. I shall be able to

CGLFO MICHIGAN:-

4 attēve LVV 2008.

REVISED 1955

—:Y7bnu2