

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

16 NOV 1937

EL'S NAME Steel Sc. Sr. "BOMBARDIER" Rpt. Nwc. No. 89381

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.)

Name of Survey

The class is subject to the stem and stem plating being repaired at the Owners' convenience.

The 2nd S.S. No.2 became due 8.28 (after an early No.3).

The vessel is laid up and the usual undertaking has been furnished.

The Newcastle Surveyors in November 1930 reported the vessel generally examined and found efficient for the present.

The vessel was not generally examined in December 1931. (See endorsement dated 29.12.31.)

A Special Survey No.3 became due 8.32.

The case was again considered on the 13th September last when the Newcastle Surveyors were requested to arrange with the owners for the vessel to be generally examined.

The same Surveyors now report the vessel examined afloat and a general examination made of the decks, hatches, hatchways, casings, coamings, machinery space, bunkers, holds, steering gear, windlass and equipment and found satisfactory.

The stem and stem plating, as above, examined and found efficient.

It is submitted action be deferred.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book



© 2020 Lloyd's Register Foundation

009256 - 009266 - 0259