

GENERAL REMARKS—(continued).

The following repairs to Damage whilst on admiralty Service have also been carried out.

Port Side Aft

Shenstone plate No 5 Cropped + No 4 plate renewed + extended.
2 Main Frames cut + upper portions removed, fained + replaced + shopped.
2 Upper deck Beams removed fained + replaced.
1 " " Stringer plate renewed + 1 fained in place.
1 Gunwale bar Cropped + part renewed.
1 Bulwark plate renewed + 1 fained in place
1 length " Rail removed fained + replaced.
4 Bulwark Stays 0° 1° 1°

Port Side Forward

Shenstone plate No 2 Fained in place.
3 Bulwark plate removed fained + replaced
2 " " " fained in place
2 lengths " Rail removed fained + replaced
8 Bulwark Stays 0° 0° 0°
1 Wash port door 0° 0° 0°

Starboard Forward

1 Bulwark plate removed fained + replaced
1 length " Rail 0° 0° 0° + 1 length fained in place.
3 Bulwark Stays removed fained + replaced.

W.S.

PARTICULARS FOR RECORD in the REGISTER BOOK.—Length of Poop ✓ ft., R.Q.D. ✓ ft., Bridge 50 ft., Forecastle ✓ ft.
(in feet and tenths). When the Poop is joined to the B.D., this should be distinctly stated.

No. and Material of Decks (if Iron or Steel) and whether wholly or partially covered with wood, and No. of tiers of Beams (this information is to be given as it should appear in the Register Book) 1 Deck Steel.

Official No. 144912; Signal Letters

State if Machinery is fitted aft No

How are the surfaces preserved from oxidation? Inside Cement + Paint.

Outside Paint.

PARTICULARS OF WATER BALLAST.—State whether the Double bottom is constructed on the cellular system or with girders on floors. Cellular System

Where Fitted.	Length. Feet.	Water Capacity. Tons.	Where Fitted.	Length. Feet.	Water Capacity. Tons.
Double bottom, aft,			Fore peak tank,		
Double bottom, under Engines and Boilers,			After peak tank,		
Double bottom, if under Engines only, Feed Water	26.0	20	Deep tank, aft,		
Double bottom, if under Boilers only,			Deep tank, forward,		
Double bottom, forward,			Other tanks, if fitted,		
	Total capacity of double bottom	20	(If necessary, furnish further information by sketch.)		

* The wells are not to be included in the lengths of the tanks.

State whether the above have been tested as required by the Rules

Order for Special Survey No. ✓

Date ✓

No. ✓ in builder's yard.

DATE OF SURVEYS
held while building
during alterations

1920. 29 Apr to 17 August. (14)

Surveyor's Signature

W.S. Way

© 2020

Total No. of Visits

Lloyd's Register
Foundation