

14 JUL 1926

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Stl. s.s. "TENDABA".

Rpt L.A.

No. 3462

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


Nature of Survey

The class of this vessel is subject to 4 shell plates being renewed in 1926 and bulkheads being then again examined.

Lloyd's Agent at Dakar now forwards a copy of a report from which it appears that the vessel has been examined in dry dock and recommendations made for repairs which are being carried out.

It is submitted action be deferred pending the receipt of a further report.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.





14.7.26.

Lloyd's Register
Foundation

009356-009361-0048