

3m. 2, 24.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

SH Co SR "FENDRIS"

Report

Gls

No.

44375

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

1<sup>st</sup> Entry

When due

Revised Rules

✦ 100 A.1. (Steel) "With freeboard"  
2 Sk (SH)

Cell D.B. E 24' 27t, DBf 28' 64t, F.P.T 84t A.P.T 18t.

F.K, 3 B.H (after peak B.H. to 2<sup>nd</sup> Sk), Cem, Lloyds A. CP. F 26'  
"machy apt"

The Certificate of Classification to be endorsed "Cargo battens not fitted" <sup>IN TWEEN DECKS</sup> and the same notation to be printed in the Register Book.



© 2020

Lloyd's Register Foundation

009387-009400-0131

In Register Book.

(Corresponding Draught

15

ft.

0

ins.

Freeboards compared and found correct by

Date