

F.E.

5c.8.11.

Received by Chief Ship Surveyor 1/6/12

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME At S S Rondo

Rpt. Sed No. 25290

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report. 24/5/92.)

Transverse No. 57.58

Depth "d" 16.91

Framing: Table No. 3 page 10

Description Bull angle as

Longitudinal No. 15359

approved

Proportions  $\frac{\text{Length}}{\text{Depth}} = \frac{13.4}{}$

Main Deck Sheerstrake as per Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed † 100A.1. (Steel) as recommended.

† 100A.1. (Steel)

1st (2d) 'Well deck'

N B. low 273c 73' n 3 + 335 f 110 4396 Sidetanks in <sup>ER</sup>

12' 7066 FPT 1195 APT 1566

FK. H.B.H. Gen. Lloyd a 60 P 28 271

B 5' F 28



009401 - 009408 - 0008